Blue highlighting = previous response to Question has been updated in this posting: Q# 5, 19, 35, 69 75, 82, 117

Delaware Department of Transportation

Yellow highlighting = previous questions answered in this posting: Q116, 119 and 120

QUESTIONS AND ANSWERS T201680104.01

ST. GEORGES MAINTENANCE YARD IMPROVEMENTS, NEW CASTLE COUNTY

Friday, September 08, 2017

Q #	# Question Answer	
130	CO A-802 detail 2 "Typical Exterior Corner @ Window" indicates a steel column. These columns are not shown on the structural plan. Please advise.	Frame corner 2x dimensional lumber. Refer to structural drawings for framing information.
129	Door elevation H on 3/MB-A-601 does not appear on the door schedule or the floor plans. Please confirm that door elevation H is not part of this contract.	Door elevation "H" is not used.
128	The door schedule on MB-A-601 list door opening 05 as 8'-0" high. The elevation of this door, elevation 6 on 4/A-601, shows the height of the door as 7'-6". Please clarify.	Elevation "6" receives the "G" gate. The "G" gate shall be the configuration as shown, with a 4'-0" bottom leaf and 3'-6" top leaf.
127	Addendum #3 reissued drawing CO-A-102, but I don't see any changes bubbled. Please clarify.	Sheet CO-A-102 was not reissued in an addendum. Sheet CO-A-101, however, was scaled and enhanced for more clarity.
126	Drawing CO-A-102 refers to an elevation drawing A-402, which is not included in the bid documents. Please issue.	Please bid per the supplied documents.
125	If the sitework breakdowns remain on the bid form, please address what bidders are to do in situations where the quantities on the bid form conflict with what is shown on the drawings.	In the case of a discrepancy in an item quantity in the plans and the bid proposal form, please bid the job based on the quantity given in the bid proposal form.
124	The bid proposal form includes dozens of sitework breakdowns. General contractors will be receiving sitework proposals throughout the day the bids are due, potentially up to the last minute. I strongly urge you to consider simplifying the bid forms.	The bid proposal form will remain as it is. If you are referring to Breakout Sheets 1 and 2, these sheets can be submitted after the bid per Prospective Bidders Note 10.

Q #	Question	Answer
123	Spec Section MB 055100 Metal Stairs requires cast in place abrasive nosings in paragraph 3.1.E.1 for metal pan stairs. Please confirm these are required? If so please provide manuf. and model number for the stair nosings.	Abrasive nosings are not required at the stairs.
122	Please provide weight / ft for the 9" steel channel called out at head and jambs of opening 09 referenced on detail 4/A303.	The steel building elements are to be determined by the metal building supplier. The design must be signed and sealed by an engineer licensed in the state of Delaware, and be submitted for approval.
121	Sheet 8 calls for 8" bollards with plastic shield while architectural drawings call for 6" bollards painted. Please confirm the steel bollard requirements.	8" bollard with plastic shield.
	Thursday, Augu	st 31, 2017
120	Addendum 3 drawings revised the MB floor plans A & S dwgs to provide a 1% sloping floor from column line 3 out to column lines 1 and 5. This creates an uneven floor condition for the installation of door frames along b line and the wash bay. Suggest making to slab finish elevation 0'-5" at all column lines with slope toward the overhead door openings.	Floor sloping shall remain as indicated in Addendum 3.
119	MB structural drawings indicate the slab on grade to be placed directly over compacted fill. Please confirm no stone is required under the slab on grade in the maintenance building.	While stone maybe used to stabilize the area depending on ground conditions during construction, stone is not required for the in place designed slab.
	Tuesday, Augus	
118	Questions and Answers #69, will the gas company bring the service and install the meters in the maintenance shop and the operation of maintenance building? Please clarify?	"The utility company will bring the gas service to the meter at the Crew Operations Building. The gas service becomes part of the contractor's responsibility at the meter at the building. See revised answer to Question 69."

Q #	Question	Answer
117	On Drawing MB-A-101, calls for 7 inch welder steel floor drain, Detail 5/A305 calls for Call B minimum 18 foot long. Specifications and manufactures are needed.	The floor drain in the wash bay of the Maintenance Building is 18'-0" L x 7" wide welded steel floor drain, Class B minimum. Manufacturers: Subject to compliance with requirements, provide products by one of the following: -Zurn Plumbing Producs Group -Watts -Smith, Jay R. Mfg Co. Wire mesh partitions spec is in Section 102213 in Appendix A. The metal stairs are detailed on Sheet MB-A-402. The spec is in Section 055100 in Appendix A.
	Please give clearer specs on stairs and Wire mesh Partitions. Wire mesh Partitions have wire mesh material has no material called out. Stairs are unclear in design.	Wire mesh partitions spec is in Section 102213 in Appendix A. The metal stairs are detailed on Sheet MB-A-402. The spec is in Section 055100 in Appendix A.
115	Please confirm Level 5 finishing is not required for gypsum board.	Level 5 finishing is not required for gypsum board. Level 4 will be the expected requirement.
114	Spec Section 092000 Gypsum Board calls for ½ thick drywall. The partition schedule details on Sheet CO-A-901 call for 5/8" drywall. Please specify the correct drywall thickness.	Crew Operations Building gypsum board shall be 5/8" thick per partition schedule.

Q #	Question	Answer
	Wednesday, Augu	ust 23, 2017
113	Since a portion of the exterior walls sheathing is in contact with the concrete slab/ foundation, should the exterior wall sheathing be pressure treated?	Wall sheathing in contact with exterior concrete slabs shall be pressure treated.
112	directly on sidewalk / porch slabs. Manufacturer recommends a 2" clearance in this condition. Please advise with alternate details.	Provide a 2" clearance at all concrete surfaces. Provide manufacturer's standard fiber cement skirt board at transition from horizontal concrete surfaces
111	Section detail 1 and 3 / CO-A-510 show a minimum clearance between grade and fiber cement siding of 2". Per manufacturer's recommendations 6" is the minimum clearance required. Please advise.	Provide minimum 6" clearance from grade for fiber cement siding.
110	Please confirm Wood trusses are delegated design and wood material specifications are left up to wood truss designer.	Confirmed, wood truss design and material specification are up to the truss designer. Contingent upon EOR approval
109	Section 061000 1.4 calls for delegated design of wood framing connections. Please advise if this is required as all connections appear to be designed.C12	Truss plate connection are delegated to the truss designer. The connections shown are all designed.
108	CO-S-001 Stud Wall Framing: notes the use of SPF # 2 or better while spec section CO 061000 2.3 B calls for bearing wall framing to be No. 1 grade Southern Pine: SPIB. Please advise the correct framing material to be used on the project.	SPF#2 or greater is acceptable for wall studs
107	Addendum 3 was issued and there were a lot of drawings changes. We request to have a change to the bid date so that we may have ample to review all the drawing changes, as well time for all of our invitees to do the same. Your consideration will be greatly appreciated.	The bid due date has been changed.
	Tuesday, Augus	
	for the Electrical Reels required at the lube bays	Provide Electrical Cord Reel similar to Woodhead heavy duty series or approved equal, with minimum 50ft of 3#12 SOW-A cable and two 125V, 20A duplex receptacles.

Q #	Question	Answer
	Please clarify the quantity and type of hose reels. According to the Lube Specs-2 oils + ATF + Hyd + Anti-freeze + Grease + Air + Electric = 8 reels. Only 7 reels are called out on the sheet MB-A-103.C11	There should be (2) oil, (1) ATF, (1) Hydraulic, (1) Coolant, (1) Grease, (1) Air, (1) Electric.
104	Lube reels are called out to be 75' on drawings but specifications require 50' please advise which is correct.	50' hose reels shall be provided per the specifications.
	In the event of a conflict between the DelDOT Standard Specs, Drawings and Project Specifications (appendix A) which document takes precedent?	Please see Section 105.06 of the DelDOT Standard Specifications, which shows the hierarchy of the contract documents.
102	Per Truss Plate Institute requirements please provide wood truss permanent bracing plans for the project.	The truss bracing information is located on general notes sheet S001. Permanent wind bracing details are shown on S502. Please note that the truss design submittal must be sealed by an engineer licensed in the state of Delaware.
101	Section 061600 Sheathing para. 3.2.B.1.a states to apply a bead of glue to wall panel edges. Please confirm this is required. Also please confirm that roof panel edges are not required to be glued.	Wall and roof panel edges are not required to be glued for this project.
100	Detail 9 / CO – S -502 calls out for solid blocking at roofing panel edges while specification section 061600 Sheathing calls for the use of H clips at panel edges. Please confirm if either method is acceptable for treatment of roof sheathing panel edges.	Either is acceptable
99	Detail $10 / \text{CO-S} - 502$ requires the use of 10 ' sheathing to execute the detail as shown. Is 8' sheathing acceptable along with solid blocking at the panel edge?	Yes, 8' sheathing is acceptable.
98	Please define locations where Hold Down Detail 8 / CO-S-502 is required. Detail 10 on same sheet states at end of walls only (8 required). Please confirm.	Hold Down Detail 8 is required at end of walls only, which is four (4) each.
97	Will panel LC, on drawing CO-E-104, remain a breaker controlled lighting panel, answered in question # 14, to be equal to Hubbell # LXBC series? These will be controlled with the use of a single PC and the Graphical User Interface Module included with this style panel, correct?	Yes, the response to question #14 describes the lighting control panel, and your statement is correct.

Q #	Question	Answer
96	Drawing MB-E-101 shows an Addendum # 3 "cloud" left of Fluid Storage Room 107, which omits the original PC show to Panel LP, circuits 2 & 4. Does the control of the building façade lighting now fall to the PC symbol, shown on drawing MB-E-201 outside of Fluid Storage Room 107 under power and special systems? This PC was not shown on the lighting plan (sheet 111) as controlling the façade lighting. Would you please clarify? It appears from the information on Addendeum # 3, and drawing #	Façade lighting is specified with integral photocell. Please refer to drawing MB-E-501 provided in addendum #3 for lighting fixture schedule. Yes, that is correct.
95	MB-E-101, Sheet Key Notes: 1 and 2, that the originally described Hubbell series LXBC lighting control panelboard is being omitted for a "standard" breaker panelboard. Is this correct? It was not mentioned in any specific detail, and the question and answers for # 13 was NOT stated to be omitted, but merely referred to Addendum # 3.	
Monday, August 21, 2017 Are the two buildings going to have the same key system? Yes, the two buildings should have the same key system?		
94	Also if they have the same key system what manufacture locks are required? Make and model. Crew building states Medeco standard key system provided by Allied Lock and Safe Maintenance Building states Factory registered, match owners existing system.	system should be Medeco standard key system by Allied Lock and Safe with Medeco Maxum 11TR50319 Residential Single Cylinder Deadbolt.
93	Project information item 5 on MB-A-100 states that a sprinkler system is not required for the maintenance building. MB-FP-101 shows a sprinkler system in the maintenance building. Please clarify.	The entire maintenance building is not required to be sprinkled. The sprinkler system is only required at the designated areas on MB-FP-101.
92	Is the gas meter on the maintenance building provided by the utility company?	Yes.
91	Please provide a specification for the metal canopy on the maintenance building.	No spec is provided as it is part of the scope of the pre-engineered metal building.
90	Item 14 of the toilet accessory schedule on drawing MB-A-401 lists a fixed shower bench. This item does not appear on the floor plan, 1/A401. Please clarify. If it is required, please indicate if it's wood, plastic laminate, or what material you would like.	Item 14 shall be located in alcove directly across from shower unit. Provide wood fixed bench.

	Q #	Question	Answer	
4° and 14°. I don't know what this means. Please clarify the height of the FRP wall paneling in room 109. The wall sections of the maintenance building (reference 1/A304) state "8°-0" long concrete apron, refer to struct." None of the other adrawings (architectural, structural, or civil) show or refer to concrete aprons outside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The clevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall. Please clarify. There are responses to several questions that refer to revised drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? A' and 14'. 2017 Belase refer to the high window and minimum across the frontage of the overhead doors, see Typical minimum across the frontage of the overhead doors, see Typical minimum across the frontage of the overhead doors, see Typical minimum across the frontage of the overhead doors, see Typical minimum across the frontage of the overhead doors, see Typical MB-S-501 for turndown details. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior clevations as Fixed Aluminum Windows. See revised specification 085113 and revised MB-A-303 & MB-A-304 in upcoming Addendum 3.			1 1	
the FRP wall pancling in room 109. The wall sections of the maintenance building (reference 1/A304) state "8'-0" long concrete apron, refer to struct." None of the other drawings (architectural, structural, or civil) show or refer to concrete apron soutside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The clevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels." Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building. If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2-please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5.	89		required.	
The wall sections of the maintenance building (reference 1/A304) state "8"-0" long concrete apron, refer to struct.". None of the other drawings (architectural, structural, or civil) show or refer to concrete aprons outside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "tanulunum windows". The wall sections refer to these window openings as "translucent panels." Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings with addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. The wage rates do not include a rate for Insulators- what rate should be used? Please provide details of the overhead doors, see Typical sminimum across the frontage of the overhead doers, see Typical sminimum across the frontage of the overhead detail 5 on sheet MB-5-501 for turndown details. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Thursday, August 17, 2017 The wage rates do not include a rate for Insulators- what rate should be used? The haudators rate would				
state "8'-0" long concrete apron, refer to struct." None of the other drawings (architectural, structural, or civil) show or refer to concrete aprons outside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels." Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triangly, August 11, 2017 Please provide details of the overhead doors, see Typical Slab on Grade detail 5 on sheet MB-S-501 for turndown details. MB-S-501 for turndown details. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. No, it is not required. Provide a schedule or quantities. Responses to the following questions have been revised to refer to Addendum 3. not Addendum 2: Questions 13, 18, 28, 30, 32, 34. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please refer to response to Question 4 and 36, and also reference the same of the maintenance buildin				
drawings (architectural, structural, or civil) show or refer to concrete aprons outside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the MB-S-501 for turndown details. Slab on Grade detail 5 on sheet MB-S-501 for turndown details. MB-S-501 for turndown details. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. Please refer to response to the following audition of the maintenance building. Friday, August 15, 2017 Please refer to response to Question 4 and 36, and also reference the meziant per UL# D716 requirements. Mindows are correctly shown on exterior elevations as Fixed Alumi			• • • • • •	
aprons outside of the overhead door or man door openings. Please clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2. please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? MB-S-501 for turndown details. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised Aluminum Windows. See revised MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also r				
clarify. The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide a spec. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Poor the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34. See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project.	88	· · · · · · · · · · · · · · · · · · ·		
The maintenance building drawings show spray fireproofing on the mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the Please provide a spect. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. This is the only location required. Provide spray applied fire resistive material per UL# D716 requirements. This is the only location required. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. The architectural drawings show a masonry foundation wall for the maintenance building. Both architectural and structural drawings show a		-	MB-S-501 for turndown details.	
mezzanine deck. Please confirm that this is the only area of this project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels." Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide a spec. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3. not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please provide details of the fencing and gate shown on drawing 5.		<u>√</u>	This is the only leasting assumed Durvide source and ind fine	
project that requires spray fireproofing. Also, please provide a spec. The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide a shects MB-A-303 & MB-A-304 in upcoming Addendum 3. Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised shuminum Windows. See revised specification 085113 and revised Aluminum Windows. See revised Smb-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Funday, August 17, 2017 Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5.	97		· · · · · · · · · · · · · · · · · · ·	
The elevations of the maintenance building refer to the high window openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the points of the first of the service of the service of the sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3. Addendum 3. Responses to the following questions have been revised to refer to Addendum 3. See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also ref	0/	·	resistive material per OL# D/16 requirements.	
openings as "aluminum windows". The wall sections refer to these window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. Sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please refer to response to Question 4 and 36, and also reference the provide a schedule or questions and provide a schedule or questions and provide a schedule or question 9. Friday, August 11, 2017			Windows are correctly shown on exterior elevations as Fixed	
window openings as "translucent panels". Please clarify and provide a specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide a sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. Sheets MB-A-303 & MB-A-304 in upcoming Addendum 3. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 and Addendum 3. Tuesday, August 15, 2017 The Insulators rate would be \$26.02 for this project.		<u> </u>	· ·	
specification if the openings are translucent panels. Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide data the maintenance building? If so, please possible in son trequired. No, it is not required. Please required. Set evised Question for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 Set revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please refer to response to Question 4 and 36, and also reference the provide details of the fencing and gate shown on drawing 5.	86		<u> </u>	
Is room signage required at the maintenance building? If so, please provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide a schedule or quantities. No, it is not required. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project.			sheets 1715 11 505 & 1715 11 50 1 in apcoming reachaum 5.	
provide a schedule or quantities. The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the potential of the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Both architectural and structural drawings show a masonry foundation for the maintenance building. Responses to the following questions have been revised to refer to response to Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide details of the fencing and gate shown on drawing 5.		<u> </u>	No. it is not required.	
The architectural drawings show a masonry foundation wall for the maintenance building, but structural drawings show a concrete foundation wall. Please clarify. Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Title Insulators rate would be \$26.02 for this project. Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Please refer to response to Question 4 and 36, and also reference the following questions have been revised to refer to the following questions have been revised to refer to addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Please refer to response to Question 4 and 36, and also reference the following questions have been revised to refer to the following questions have been revised to refer to addendum 3.	85		, ,	
Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please refer to response to Question 4 and 36, and also reference the please reference		<u>- </u>	Both architectural and structural drawings show a masonry	
Thursday, August 17, 2017 There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to the following questions have been revised to refer to Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please refer to response to Question 4 and 36, and also reference the Please	84	maintenance building, but structural drawings show a concrete	foundation for the maintenance building.	
There are responses to several questions that refer to revised drawings to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Triday, August 11, 2017 Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. The responses to the following questions have been revised to refer to Addendum 3, not Addendum 2: Questions 13, 18, 28, 30, 32, 34 See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the fencing and gate shown on drawing 5.		foundation wall. Please clarify.		
to be included in addendum #2 but there doesn't seem to be any new drawings with addendum #2- please advise. Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the sta		t, c		
Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. The Insulators rate would be \$26.02 for this project. Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the state of the fencing and gate shown on drawing 5.		<u> </u>	1 -	
Tuesday, August 15, 2017 The wage rates do not include a rate for Insulators- what rate should be used? The wage rates do not include a rate for Insulators- what rate should be used? Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the provide details of the fencing and gate shown on drawing 5.	83	•	Addendum 3 , not Addendum 2: Questions 13, 18, 28, 30, 32, 34	
The wage rates do not include a rate for Insulators- what rate should be used? See revised Question 5 response issued 8/17/17. The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the				
be used? The Insulators rate would be \$26.02 for this project. Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the				
Friday, August 11, 2017 Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the		<u> </u>	•	
Please provide details of the fencing and gate shown on drawing 5. Please refer to response to Question 4 and 36, and also reference the	82	be used?	The Insulators rate would be \$26.02 for this project.	
\perp A \mid \perp		Friday, August 11, 2017		
1 1 1	01	Please provide details of the fencing and gate shown on drawing 5.	Please refer to response to Question 4 and 36, and also reference the	
	61		DelDOT Standard Specifications, Section 727.03.4.	

Q #	Question	Answer
80	Paragraph 2.4.C of the Wire Mesh Partitions, section 102213, of the maintenance building mentions wire mesh ceilings. The drawings do not show any wire mesh ceilings. Please confirm that there are none.	Confirmed. There are no wire mesh ceilings in the maintenance building.
79	Paragraph 2.4 of the Thermal Insulation spec, section 072100, of the crew operations building mentions spray foam insulation. Please confirm that there is no spray foam insulation on this project.	Spray Foam Insulation is only required in miscellaneuous voids and cavity spaces where required to prevent gaps in insulation, per 072100-3.3C.
78	There is a spec section for bituminous damproofing at the crew operations building, but none is shown on the drawings. Please clarify.	Provide damproofing on foundation walls.
77	There is no designation for fire ratings at the crew operations building. Please confirm that none of the wood wall framing, sheathing, trusses, etc. at the crew operations building has to be fire rated.	No fire ratings required.
76	Paragraph 2.8 of spec section 033000 – Cast-in-Place Concrete describes a slip resistive finish of aluminum oxide aggregate. Please confirm that this does not apply to this project.	This note does not pertain to this project. All concrete left exposed at the completion of the project shall be treated with a clear penetrating acrylic base polymer capable of preventing infiltration of water born chlorides such as Conspec #1 by Conspec Marketing & manufacturing company or approved equal.
75	The project specs include Highway Construction prevailing wage rates. The majority of this contract is building construction. Please clarify.	See revised Question 5 response issued 8/17/17. Please see responses to Questions 5 and 35.
74	Please provide specifications for the overhead crane at the maintenance building.	The spec for the overhead crane will be provided via addendum.
73	Card readers and security work is typically by the owner. Please clarify if security and card readers are part of this contract.	The card readers are excluded, but the conduit rough in is the responsibility of the contractor.
72	Please provide specs for the fiberglass column covers at the crew operations building.	Provide 10" round plain Permacast Column bu HB&G with colonial cap and base, or equal.
71	Do the closets in room 107 and 110 of the crew operations building receive a shelf and rod?	Provide wooden shelf and metal rod in closets 107 and 110 of the Crew Operations Building.
70	Drawing 18 shows a production well. Is this part of the contract? If so, please provide additional information (detail, specs, depth, etc.).	The production well is to be installed by the contractor. Well production must meet 100 GPM. All costs associated with the design and construction of the well is incidental to Item 614508 - Water Main and Accessories.

Q #	Question	Answer
	Who owns the gas service on Drawing 18? Will the owner and utility	"The owner will pay the utility company to bring the gas all the way
69	company provide this? Or is it part of the contract?	to the meter at the Crew Ops Building."
0)		Delmarva power will install the gas service to a location on the
		south of Lorewood Grove Road for tie-in to the site.
	Note 2 on Drawing 18 states that the electrical service along	a) The work for getting the electric service from the pole across the
	Lorewood Grove Road will be constructed by others. Key Note 1 on	street to the site is the responsibility of the contractor.
	Drawing 21 states to jack and bore two 5" conduits under Lorewood	b) Delmarva owns the transformer and meter. Delmarva will bill the
	Grove Road. Please clarify the following regarding the electrical	owner for that work.
68	service:	
	a. Please clarify what the owner and Delmarva owns, and what is	
	expected to be included in this contract. A revised drawing 18 would	
	help.	
	b. Does Delmarva own furnishing and installing the transformer? Or	
	will Delmarva furnish the transformer and the electrician install it?	
	Drawing 18 has a note that states, "ITMS conduit and junction wells	The contractor is responsible for the ITMS conduit on the site but
	to be installed by others". Note 4 on the same drawing states, "ITMS	not the cables. The note on Sheet 18 that states, "ITMS conduit and
67	conduit to be installed by contractor". Please confirm if the ITMS	junction wells to be installed by others" is referring to others
	conduit is part of this contract.	providing the ITMS conduit along Lorewood Grove Rd up to the
		junction well at the northeast corner of the yard.
66	Please confirm that the box noted as "Brine" on drawing 18 is not part	
	of this contract. If it is part of the contract, please provide specs.	described on Sheet 5 for the Brine Pad.
65	Does the contractor own storm water management as-builts?	Yes, the storm water management as-builts are the responsibility of
		the contractor.
64	Does the contractor own CCR reports?	The contractor is not responsible for writing the reports but must
		have a CCR certified representative at the required walkthroughs.
63	Please provide a specification for the flag pole. Also, please confirm	A flag pole spec is provided under Item #763502 'Site Furnishing.'
	that the flag itself is not part of the contract.	The flag itself is not part of the contract.
	Please confirm that testing of soils, concrete, steel, etc. is by the	Quality assurance, geotechnical observation, and special testing and
	owner.	inspections will be provided by DelDOT. Per Section 106.02, "The
62		contractor is responsible for quality control of the materials as
		defined in Division 1000 and is responsible for the condition of the
		materials until the project is accepted."

Q #	Question	Answer
61	Please confirm that updating CAD files with as-built changes is not part of the contract.	Correct, it is not part of the contract.
60	Please clarify the railing composition. Detail 4/MB-a-302 shows a three line rail. Detail 1/MB-A-305 calls out expanded mesh infill. Detail3/MB-A-402 shows a three line rail, but calls out 1" pickets.	Please see updates to railing in upcoming addendum.
59	Please refer to detail 2/MB-A-305. As shown the joists do not have sufficient bearing since the joist bearing plate is not shown (6"). Instead could a HSS8x2x1/4 be used as a screed as well as a base for the railing? It could be welded to the joist, assuming a 5" seat height was o.k	See revised sheet MB-A-305 for revised detail.
58	Please refer to spec MB 051200. Can the AISC Certification be waived?	The requirement for the installer to be certified (MB-051200.1.7.B) can be deleted. All other certification requirements in the section shall remain.
	Wednesday, Aug	ust 09, 2017
57	On A-901 (door schedule) notes both hardware set 11 and 12. These sets do not exist on the hardware schedule (spec 87100) Please issue correct hardware sets, with door numbers.	There are two (2) hardware sections- one for the Crew operations building (designated CO), and one for the maintenance building (designated MB). Both sections correctly reference their respective drawings. Bidders should ensure they are referencing the correct hardware section.
56	Hardware schedule in spec 87100 does not list any of the correct door numbers.	There are two (2) hardware sections- one for the Crew operations building (designated CO), and one for the maintenance building (designated MB). Both sections correctly reference their respective drawings. Bidders should ensure they are referencing the correct hardware section.
55	Openings 102B and 109 are both on the floor plan but not on the door schedule.	upcoming addendum.
54	Sheet CO-E-201/MB-E-201, General Note 6, please clarify the ownership of all door hardware as this is not normally part of the electrical package.	Electrical contractor shall provide all required electrical conduits and boxes.
53	Sheet CO-E-002/MB-E-002, General Note 49 indicates PVC coated rigid to be used in areas prone to pollution. Please advise what areas are prone to pollution.	This is a general note; areas prone to pollution are outdoor areas. However, there should be no exposed outdoor conduits in these buildings.

Q #	Question	Answer
52	Sheet CO-E-002/MB-E-002, General Note 41 & 46 state the use of galvanized rigid conduit but specification section 26001 2.1, f, a-f indicate the use of EMT as well as MC cable. Please clarify.	All wiring shall be installed in conduit. The use of EMT is allowed only concealed in ceilings and interior walls and partitions.
51	Sheet CO-E-002/MB-E-002, General Note 38 please clarify the ownership of all the devices as these are not normally supplied in the electrical package.	General note suggests a coordination with mechanical division to provide the control and power wiring for the mentioned devices. It is not referring to the devices specifically.
50	If there is going to be a networked Fire Alarm system fiber optic cable must be run between each building to enable communication between the Crew Ops FACP & Maintenance Shop FACP.	The site wiring between buildings will be done by others through a separate contract.
49	Drawing CO-E0401 & Drawing MB-E-401 each reference Schematic 1 – "Fire Alarm Riser Diagram". This schematic does not display any sort of network capability between the two buildings. Furthermore it references "Autodialer with two dedicated phone lines to UL Listed Central Station". Per Delawares 2016 Fire Code update two dedicated POTS lines are no longer an acceptable method of communication/monitoring.	Provide a fire panel that will utilize an Ethernet (network) connection as the primary and a POTS or Ethernet as the secondary connection.
48	Divison 28 - Section 283111 - Page 1 - Paragraph 2: "1.2 System Description" States: "Non-coded, addressable system, with multiplexed signal transmission dedicated to fire alarm service only". In reference to the "multiplexed signal transmission" is it the intent of the owner to have a networked Fire Alarm system in the multiple buildings, to enable the owner to only pay one monitoring fee for the entire site.	Yes, it should be networked. See Question 50.
47	Section 260001, 2, F, h – electrical feeder distribution conduits within building shall not be in the concrete slab or underground. Please confirm all conduits will stub up on the exterior of all buildings and enter building via LB type conduit fitting.	Section 260001, 2, F, h will be amended in upcoming addendum. Please provide underground conduits for building incoming service as shown on site plans.

Q #	Question	Answer
	General Note: all metal building Engineering & construction by metal building manufacturer. What is their scope of this?	The PEMB manufacturer is responsible for all components of their building system from the column baseplates up, please refer to "Metal Building System" general notes on S001 and the specs.
	Are they responsible for the steel for the overhead crane? If not what column and beam sizes are requested?	They are responsible for the overhead crane.
46	Are they responsible for the steel protective angle at all door openings as noted on 1/MB-A-304?	They are not responsible for the protective steel angle at the door openings in the SOG.
	Are they responsible for the 9" channel for the overhead door? Presume Yes?	They are responsible for the 9" channel for the overhead door and for the steel lintels.
	Are they responsible for the steel lintels as noted on 6 &7/MB-A-602?	
45	This job bids in one week. When will the pre-bid meeting minutes be posted?	Please see addendum No. 2.
	Monday, Augus	t 07, 2017
44	Sheet 29/116 CO-A-101 the stated scale of ½"=1"0" does not match the string dimensions on the plan. Please advise Sheet 71/116 MB-A-101 stated scale of 1/8" = 1"0" does not match the string dimensions on the plan Sheet 90/116 MB-S-101 stated scale of ½" = 1"0" does not match the string dimensions on the plan Please correct the drawings so that the stated scale matches the drawing dimensioning.	Sheets will be updated via addendum.
	Friday, August	
43	Please provide Automatic Temperature Control Specifications for the Maint Building and Crew Ops building	Specifications for each building will be included via addendum.

Q #	Question	Answer
42	on the wall the wash bay. Assume these are intended to indicate Carbon Monoxide sensors however no specs or explanation is provided in the documents. Also the sequence of operation on sheet MB-M-701 does not acknowledge the CO sensors. Please advise the manufacturer/ model of the CO sensors and their interaction with the	Specifications for the CO sensors are included in section 233300.2.8.C. The shop and wash bay exhaust fans shall energize in the event of a CO reading above setpoint (25 ppm, adj.).
41	building mechanical system Is there a boring log available that shows existing topsoil depths and the thickness of the existing parking lots hot mix and stone?	Boring logs will be posted to the website.
40	Sheet MB-E-101, door E6 indicates a XWP fixture – is there a catalog number for this fixture?	Provide waterproof exit sign similar to Barron-Exitronix Series NAV-NC-R-1-W-IH1 or approved equal.
39	Sheet S-E-205, detail 4 and 5; with using the braided strap to bond the lid this will limit the swing of the lid when opening – are Quazite style boxes acceptable?	± ±
38	Sheet S-E-204, detail 4; shows 24" min cover on two (2) 5" conduit. This is primary HV cables – is the 24" min cover correct?	Sheet S-E-204, detail 4; shows 24" min cover on two (2) 5" conduit. Coordinate exact primary incoming service with Delmarva Power as indicated in General Note No. 1 on sheer S-E-201.
37	Sheet S-E-201, keynote 10; need to identify where the feed will come from for this panel as well as the size of the panel and what size MCB.	12 circuits panelboard with 30A Main Circuit Breaker is indicated on Drawing S-E-201 key note 10. Feeder for this panel is indicated with a drawing symbol for Conduit/Wiring description shown on drawing S-E-201. Please see Conduit/Wiring schedule ID's "F", "J", "N" and "O". on drawing S-E-202, which indicated that the panel is fed from panel "CO". located in Crew Operations building. Refer to drawings for Crew Operations building, sheet CO-E-501 for "CO" panel board schedule.
36	Please specify. What type gate is used for the 30' opening in the fence Steel slide, Alum. Slide or Double Drive Swing gate.	For the gate at the south end of the yard, use a double swing with pad lock, having a total width of 20'.
35	The wage rates provided don't have a rate for plumbers. What rate should be used?	See revised Question 5 response issued 8/17/17. The rate to be used for Plumber for New Castle Highway is \$30.94. for the T201680104 project.

Q #	Question	Answer
34	On sheets MB-A-303 detail 2 and on MB-A-304 detail 1 shows a "translucent panel 3'0"" over the coiling doors but on the elevations they are shown as "aluminum windows with insulating glass". The window details don't show these openings at all. Please clarify what these windows are.	See response to Question 30.
33	Please confirm no slope and no floor drains are required in the Repair Shop Area Floor 108.	The maintenance building floor should be sloped approximately 1% (1/8" per foot) with the crown along Column 3. This update/change will appear via Addendum in the concrete spec to include flatness criteria.
32	Section MB22124 – 2.12.B Lubrication Tank Schedule does not match the tank sizes on sheet MB A-103 for the same fluids. Also, the tank schedule in section MB 22124 does not address the waste oil and waste hydraulic oil storage tanks. Please advise with specifications for the waste oil and hydraulic oil tanks and confirm all tank sizes and quantities.	Remove the 250 gallon double walled waste oil recovery tank (Equipment #24 on Sheet 73). Still provide the 500 gallon double walled hydraulic recovery oil tank, based on spec provided in upcoming Addendum 3. The correct tank quantities and sizes are as follows (note: they are incorrect on sheet 73): (1) 15-40 Motor Oil: 250 gallons (1) 10-30 Motor Oil: 60 gallons (1) Coolant: 120 gallons (1) Lubricant oil: 55 gallons (1) ATF: 120 gallon (1) Hydraulic Oil: 250 gallon
31	Is DelDOT providing the geotechnical observation, special testing and inspections, and field quality control for the project?	inspections will be provided by DelDOT. Per Section 106.02, "The contractor is responsible for quality control of the materials as defined in Division 1000 and is responsible for the condition of the materials until the project is accepted."
30	Maintenance Building exterior elevations indicate Aluminum Storefront framing and glazed transoms above the overhead doors. The openings are not addressed on the typical window and door detail sheet MB A 601 furthermore, Spec section MB-085113 covers operable window only not fixed windows as indicated. Section detail 2/MB-A-303 states translucent panel at transoms. Please clarify the transom material.	Windows are correctly shown on exterior elevations as Fixed Aluminum Windows. See revised specification 085113 and revised sheets MB-A-303 & MB-A-304 in upcoming Addendum 3.

Q #	Question	Answer	
29	Please confirm the jack and bore for the electrical service running under Lorewood Rd is to be provided under this contract.	The work for getting the electric service from the pole across the street to the site is the responsibility of the contractor.	
28	Sheet 5 Wash Pad Forebay detail shows 6" p.c.c. concrete noted as pay item 610009. This pay item is not included in the Schedule of pay items in the proposal package. Please advise	Item #610009 PCC Masonry, Class B, will be added in the upcoming Addendum 3 .	
27	Please provide the width of the footing for the monument sign	The footing shall be 12'-0" L x 3'-0" W.	
26	Confirm no reinforcement is required in the 12" thick concrete paving section detail B shown on sheet 5	Confirmed, it is not required.	
25	Please provide length and width dimensioning for the tank pad, fueling apron, brine pad and electric pad.	The tank pad will be 22' X 17' with a 4.8' X 10' connection to vehicle area (Approx 422 SF). The brine pad will be 30' X 20' (600 SF). The electric pad will be 25' X 50' (1250 SF).	
24	Pay item 501006 calls for a 12" thick pad and is to be used to pay for the tank pad, electric pad, brine pad and fueling apron. The curb details for the tank pad appear to call out an 8" thick slab. please advise with the correct thickness of the tank pad.	The correct thickness of the tank pad is 12", therefore, the curb encasement should read "12" on the front face, and not 8".	
23	Please detail the scope of work to be included in item 763504	Refer to special provisions for Item #763504.	
22	The schedule of pay items does not include clearing and grubbing, excavation and embankment, and site electrical conduit and wire. Please advise.	These items are paid for under Item #763504 Site Work.	
	Tuesday, August 01, 2017		
21	Drawing CO-A-301 and Table of Contents call for sheet vinyl flooring, however spec section 096516 is not included. Please advise.	The spec for vinyl sheet flooring is in Appendix A on pages CO-096516-1 to CO-096516-4.	
20	The advertised contract duration of 620 days seems excessive for the scope of work to be completed. If the successful bidder based their proposal on a contract duration less than the advertised duration what are LD's and damage claims based from? The advertised duration or the agreed upon construction schedule?	The contract shall be bid according to the advertised contract duration. As per Section 108.04.A, "Fully use, but do not exceed, the specified Contract duration in the Progress Schedule Chart (PSC)."	

Q #	Question	Answer
	The proposal packet contains only the Delaware State Prevailing Wages for "Highway Construction". Please confirm that these are the only wages to be used for the project AND that "Building Construction" Wages are not to be used for the construction of the	See revised Question 5 response issued 8/17/17.
	Driver's Training Building and Maintenance Shop. Friday, July 2	PR 2017
1.0		Provide a 5'x5'x1'-6" column footing at gridlines D2 & D4 on sheet
	no footings shown for these on the foundation plan MB-S-101. How are they being supported?	S101 per detail 2/S501. See revised sheet MB-S-101 in upcoming Addendum 3 .
17	There is no spec for the stone veneer on the sign, what product is to be used here?	
	<u> </u>	a) Panel board is designed to be surface mounted, provide a strut channel structure for panel installation. Exact panel location shall be coordinated in field with all trades involved.
	b. What additional branch breakers are required for the fueling station panelboard?	b) Provide six (6), 20A, 120V, 1 pole, branch circuit breakers.
	I would like to ask for a clarification on the electrical panelboard	Per manufacturer catalog information, Killark circuit breaker
	feeding the fueling station. After reviewing Sheet drawings # 10, and	panelboard is designed for Class I, Div 1&2. The 12 circuit panel
	# 11, of the Construction Details, plus drawing # S-E-201, Key Note	board specified in key note 10 on dwg S-E-201 fits in the Hubbel
	10, I was looking for any mounting details, or a defined	Killark Distribution Circuit Breaker Panel Board B7L/B7P Series -
	"Classification" of the requested Panelboard for the Fueling Station.	B7 P 20 3 12 MBB 30- there are not catalog numbers for Class 1,
15	Key Note 10, refers only to a panel manufactured by Hubbell –	Division 1 and Class 1, Division 2 separately. Same situation occurs
13	Killark, in a NEMA 4X enclosure, but also refers to providing sealing	for the Fitting Hubbell – Killark # ENY-3 which is suitable for
	fittings for Hazardous Locations, equal to Hubbell – Killark # ENY-3.	installation in Class I, Div 1&2. Exact location of the panel shall be
	What classification do we have to adhere to for the panelboard, and its	coordinate in field, with all trades involved Motor Fuel Dispensing
	mounting location?	facilities are Class I as defined in NEC Table 514.3(B)(1), The
	Will it be Class 1, Division 1 or perhaps Class 1, Division 2, etc.?	Division 1 or 2 depends of the location of the electrical equipment
		as defined in NEC Table 514.3(B)(2).

Drawing # CO-E-104, detail # 5, identifies Panel LC as Hubbell # LXIN-32-16-08 with enclosure # LEXAN-32-S, which also refers us to Drawing # CO-E-501 for the Panel LC schedule.

(a) The electrical single-line diagram, on Drawing # S-E-301, shows Lighting Control Panel "LC" fed by a 40A/3P branch breaker, from panel CO (9,11,13). The Hubbell style LXIN panel is not like the style LXIN panel whereas you provide a feeder to a vertical has fed morel.

(a) The electrical single-line diagram, on Drawing # S-E-301, shows Lighting Control Panel "LC" fed by a 40A/3P branch breaker, from panel CO (9,11,13). The Hubbell style LXIN panel is not like the style LXBC panel whereas you provide a feeder to a vertical bus fed panel and tap branch circuits from it in the same way a typical power panelboard would work. The LXIN series uses relay modules that receive the feeder circuit from a remote panelboard and return the load circuit from the same relay, acting as a switching relay only. Would you rather use the same style panel, LXBC?

Panel LXBC is accepted. Provide lighting panel similar to Hubbel LXBC -1-IL-B-30-H-1S.or approved equal. For spare breakers provide 50% controlled breakers and 50% non-controlled breakers.

Q #	Question	Answer
	Drawing # MB-E-501 (Sheet No. 116) provides the panel "LP" schedule, which has been identified, on Drawing # MB-E-101 (Sheet No. 111) as a Hubbell # LXBC-1-1L-B-18-H-1S with # LXTB graphical interface user or equal. The Hubbell series LXBC panel uses "controlled" as well as "non-controlled" circuit breakers.	
	(a) Which type breaker are we to supply for the six "spares" in Panel LP?	a) Provide 3 controlled breakers and 3 non-controlled breakers.
13	(b) Should these be split, whereas we provide three of each type, or another variation?	b) Same as a) above.
	(c) In an attempt to properly identify which breakers in panel LP were to be "controlled" or "non-controlled" would you please clarify the following "branch circuit loads"? Service Bay # 3 (Drawing MB-E-101) identifies LP-9 as the feeder circuit. Service Bay # 5 identifies LP-11 as the feeder circuit. Panel schedule LP identifies circuit # 7 feeding Lighting Bay # 3, circuit # 9 feeding Lighting Bay # 5. Would you please indicate which circuit identifier should be changed?	c) Circuits would be labeled as indicated on "LP" Panel board schedule. Circuit # 17 shall be included to serve bay #1. See revised sheet MB-E-101 and MB-E-501 in Addendum 3.

Q #	Question	Answer
13	(d) The above is not a big deal, but it also extends to Panel LP circuit # 11, identified as feeding the Mezzanine. Drawing # MB-E-102 shows the mezzanine lighting fed from circuit LP-11. Drawing # MB-E-101 identifies circuit LP-11 as feeding Service Bay # 5. After clarifying paragraph (c) above, would it be possible that the mezzanine lighting would be controlled on circuit LP-15? The mezzanine lighting is a "non-controlled" breaker load and shown to be fed by 3-way switches. Circuit LP-11 is a "controlled" breaker load, as identified on Drawing MB-E-101, represented by switch Se. (e) Drawing # MB-E-101, Sheet Key Note # 3, identifies the Lighting Control Switches to be similar to Hubbell LX Sentry Switch, toggle style with locator light, or equal. Hubbell has discontinued the LX Sentry Switch style, and replaced them with the LXSW series (spec sheet attached). This becomes important for a couple of reasons. The replacement style is wired using Belden # 8471 cable, and not standard wiring as did the older "Sentry" design. This should be noted on the drawings. The new switch design also brings up the question (see spec sheet) do we furnish [5] LXSW1LPW, or [1] LXSW5LPW at each of the two locations, designated as SaSbScSdSe, on Drawing # MB-E-101, to control the Service Bay Lighting Circuits?	d) Service Bay #5 will be fed by circuit LP-9 and Mezzanine by circuit LP-11 following LP panelboard schedule. Final circuit identification shall be documented on as-built drawings. See revised sheets MB-E-101 and MB-E-501 in upcoming Addendum 3. e) Since the mentioned key note also refers to switches compatible with the lighting control panel, LXSW should be used. LXSW5 is a good option for this application.
	Monday, July	24, 2017
12	The Overhead Crane in the Maintenance Building is called out as by	The spec will be updated in upcoming Addendum 3.
11	Detail 2 on A-502 calls for a W12x45 to support various mounted equipment. Assuming that this beam has been designed by the project engineer already and it will attach to the building columns. Can end beam reactions/loads be provided which the PEMB columns will support?	The W12x45 beam with 8 hose reels should be designed to see a 1kip Live Load and 1Kip Dead Load.

Q #	Question	Answer
10	The drawings show a 5 ton overhead crane running from grids 2-4 and spanning between grids C-E. There are 6 columns shown on the drawings to support the crane runway steel. It would be a more efficient design if this crane were underhung and supported from the steel above.	If awarded, submit a value engineering proposal/ substitution request per the contract documents that outlines the proposed change in design and cost implications for all systems. Request shall meet all the requirements of Specification Section 012500. The deflection & lateral drift requirements per the crane manufacturer must be met. Support for equipment reels, which share the columns in question, must also be factored into the proposed change (see MB-A-103, MB-A-302, MB-A-502, etc.). Equipment must remain at heights indicated on contract documents.
9	Are the CMU walls designed with bond beams so that the walls are braced horizontally between building columns and a structural member on top of the wall is not required for support? The drawings appear to show a bond beam at the top of the 4'-8" high wall and two rows on bond beam for the 1'-8" high wall. The drawings do call for a 9" metal channel but I assume that this channel will be used to support the metal exterior panel and interior liner panel only? This channel is not intended to brace the top of the CMU wall?	Yes - the bond beams will be sufficient to brace horizontally without the structural need for support from above. Correct - The 9" channel is for the wall system per the PEMB Manuf. and is used to support the exterior and interior panels only.
8	The drawings are calling for the simple saver insulation system for both the roof and walls. This system is labor intensive and encapsulates the roof purlin cavity making it very difficult to accommodate attachments for MEP. Will other systems be allowed as long as they meet the required U-values and energy code requirements Just need to know what energy code is being followed and what are the required tested u-values?	JM Simple Saver system (or equal) is required for the roof. Code required U-Factor for roof is .032. Other insulating systems are permitted for the walls as long as they meet the code required U-Factor of .052. Metal liner panel required for walls per drawings.
7	What are the required tested u-values for both the roof and wall insulation systems to meet the energy code? (RFI question)	Code required U-Factor for Roof is .032. Code required U-Factor for walls is .052
6	On sheets CO-S-001 and MB-S-001 note 6 under the Foundation heading says "If soil of this bearing is not encountered at the elevations indicated on the contract drawings, footings shall be lowered or increased in size as directed by the structural engineer." How will the extra work be compensated if this occurs?	Follow Section 104 of the DelDOT Standard Specifications.

Q #	Question	Answer
	The prevailing wage rates provided are for highway construction, will	8/17/17: The Dept of Labor has issued a Multiple category
	these be the rates that are applied to the building construction on this	construction project consisting of Highway and Building
	project?	Construction prevailing wage rates. The revised wage rates are
5		included in Addendum 3. The building rates apply to Building
5		Renovations Including Chain Link Fence and Sign. All other work
		is covered by Highway rates.
		Yes, Highway Construction are the wage rates issued by the
		Department of Labor for this project
	Thursday, July	
	Please clarify the new Fencing around the property. There is no plan	Furnish and install 8' high, 9 gauge galvanized chain link fence
	detail and specs are general not specific.	with 1'-0" high three (3) strand barbed wire on outward facing arms
		in accordance with DELDOT standards specifications. End posts
		and pull posts are to be 3" OD SS40 and intermediate posts 2-1/2"
4		OD SS40. Brace railings are to be 1-5/8" OD SS#40. All corner,
		brace, and gate posts are to have truss rod assemblies. The fence
		should have top and bottom 7 gauge tension wire attached with hog
		rings. All concrete is to be truck delivered Class B mix concrete
		crowned to promote runoff of water. All other material should be
	On plan sheet 4:	The state (DELDOT) will remove the salt from the existing salt
	Demolition D-2 - will the contractor remove the salt from the existing	barn, NOT the contractor.
	salt barn?	
3	Demolition D-4 - 3 tanks are on site. Are they all to be removed?	D-4 Should state, "Steel Frame Tank to be removed by others.
		However, contractor shall remove the concrete pad.
		D-5 Should state, "Remove existing hydrant."
		12 2015
	Thursday, July	
2	Is DelDOT going to make the building items specialty items so the	This will be addressed at the Pre-Bid Meeting.
	prime contractor can meet the self-performance requirement?	

Q #	Question	Answer
	Page MB-283111-3 of the Fire Alarm Specification, section 2.2 reads	The Honeywell Notifier Fire Alarm System is acceptable to the
	"Manufacturers: Subject to compliance with requirements, provide	owner. For future requests like these, please follow Project Bidders
	products by Edwards Signaling and Security Systems, a GE Company	Note #15, which states "There are various manufactures listed
	or equal as pre-approved by the Owner."	throughout the Technical Specifications in Appendix A. In addition
1		to all listed manufactures, you may submit an 'Approved Equal' to
	Our company is requesting to be "pre-approved by the Owner" to	the Department for review and approval/disapproval. Your request
	provide an equal "Honeywell Notifier Fire Alarm System".	must list's the page number, paragraph and section of Appendix-A
		that you want reviewed. Send your 'Approved Equal' request to: dot-
		ask@state.de.us."