

Delaware Department of Transportation
QUESTIONS AND ANSWERS
T201480201.01
Woodland Ferry Repairs, South, 2014
September 23, 2013

Q #	Question	Answer
10	Is this contract subject to Maryland State sales tax?	Yes.
9	What does the phrase “Payment is incidental to paint items” mean. Found in several locations in Item F.	These minor items will be paid for under the Prime and Paint items and should be included in the price of the Prime and Paint items.
8	The work scope specifications read.... F. Painting...”remove all rust and areas of paint failure, prime, and overcoat the entire exterior of the ferry” The bid Form only allows for Prime and Paint 450 sq. ft. above the W.L. and 2010 sq. ft. below the W.L. So do we just bid for this amount of Sq. ft. listed and the number of coats of paint as described in the Paint table p. 15? And if that is true how do we allow to paint “lettering, numbering, and handles shall be repainted in its existing colors.....”	Bid the quantity in the bid sheet

September 18, 2013

7	Are the existing exterior stairs, railing, and captain's house included in the 'exterior paint above waterline' quantity on the bid sheet?	No, they are not included in the bid quantity. Please bid the quantity in the bid sheet.
6	On Page 13, Section E, Note 3, what is the model number of the existing fairleads?	Skookum Blocks and Rigging, Roller RFB-1 with Bushing, Item #00-510001
5	On Page 13, Note 5, please clarify what grease fittings are being referred to and where they are located.	The grease fittings are on the hinge pins located on the ramps and can be seen in the gap where the ramp meets the deck. Each ramp hinge is to have Teflon grease lines installed and run to an access box which is to be mounted on the nearest upright post. This is to be done on both ramps, for all hinges. Note D-5 on page 13 describes the replacement of damaged grease fittings on the Bethel side, but can be ignored as fulfilling Note D-4 on page 13 will be effectively replacing the grease fittings.
4	On Page 14, Note 7, is the existing hydraulic pump to be replaced?	Yes.
3	Is the friction coating on the ramps the same as that of the deck?	Yes.
2	Is friction coating to be applied to both sides (top and bottom) of ramps?	Friction coating is to be applied to top of ramps only.
1	Please provide a picture of the idler pulley assembly.	See attached photos.



