

Delaware Department of Transportation

QUESTIONS AND ANSWERS

T201280204.01

STORMWATER POND MAINTENANCE, CENTRAL/KENT COUNTY

Friday, October 24, 2014

Q #	Question	Answer
4	Are there any restrictions in putting equipment in the bottom of the ponds?	No.
3	At the P112 area at the south side of Scarborough Road, how far back from the end of pipe are we responsible to maintain the ditch?	The work is limited to the outfall energy dissipator as noted on plan sheet 19.
2	At BMP 211 when I align myself with the turn arrow I do not see P112 on the south side of Scarborough Road. and this pipe be exposed so we can identify the work area?	Removal of the trees and exposure of the outfall of pipe 112 is a contract item paid under 201000 Clearing and grubbing.
1	Does Item 271501 include the sediment removal in the pond or is the sediment removal paid by the CY with Item 02000?	Sediment Removal is paid under item 202000.