

Delaware Department of Transportation

**QUESTIONS AND ANSWERS**

**T201508305.01**

**SIGNALIZED MEDIAN CROSSOVER SIGNING AND PAVEMENT MARKING UPGRADES, STATEWIDE**

**Friday, November 04, 2016**

<b>Q #</b>	<b>Question</b>	<b>Answer</b>
12	Various recommendations require “replacing” and existing sign panel. Do these replacements require a new post?	<i>Response forthcoming.</i>
11	At what width or total square footage does a sign require a 2 post installation?	<i>Response forthcoming.</i>

**Wednesday, November 02, 2016**

10	For signs that are being removed and not replaced, how do you want the holes filled?	<i>Response forthcoming.</i>
9	It’s stated in the contract that all sign aluminum is to be .125 thickness. Is this accurate? That’s very thick for smaller signs and is typically only used for signs 48” wide and wider.	<i>Response forthcoming.</i>
8	What relevance does the Construction Engineering line item have in the bid?	<i>Response forthcoming.</i>
7	Do 36" signs require two posts?	<i>Response forthcoming.</i>
6	Item number 749532 SUPPLY OF FLAT is that inclusive of 749556 or separate signs to be delivered to DELDOT?	<i>Response forthcoming.</i>
5	You say .125 thickness but MUTCD is .080 Can you clarify?	<i>Response forthcoming.</i>
4	Do we pay sign installers Laborer rate or Sheet Metal worker rate?	<i>Response forthcoming.</i>
3	If item numbers 749532 and 749570 are for delivery of stock signs and posts and item number 749556 is for installation of signs and posts, when would The Department take delivery of item numbers 749532 and 749570?	<i>Response forthcoming.</i>
2	Please explain how item # 763501 applies to this project.	<i>Response forthcoming.</i>

Q #	Question	Answer
1	<p>The retroreflectivity requirements for Type IX sheeting seem to have typos. For example, the highlighted number in the table below should require 75 per ASTM D4956, as opposed to 275.</p> <p>The retroreflectivity requirements for Type XI sheeting do not match ASTM D4956.</p> <p>The warranty requirements are vague, but seem to require 12 years of labor replacement.</p>	<p><i>Response forthcoming.</i></p>