

CONTRACT NO. T201280104.01
CLARIFICATION
MAY 12, 2014

Clarification to Question No. 80:

We are requesting a clarification of the answer to question #80 in question and answers dated 05/09/2014. Does that answer indicate that there are not toe walls in the pad or that there are toe walls but the contractor is not paid for the toe wall concrete?

Response:

The term toe wall generally refers to a small retaining wall. There are no permanent retaining walls in this contract. The utility pad is a turndown type slab (see Sheet 20 "Utility Pad Section"). Item 602001 includes all costs necessary to construct the pad as shown on the plan. Item 602001 is a unit cost item and will be paid per unit as stipulated in the contract documents.