Contract No. T201880207.01 FAP No. Various Woodland Ferry Renovations, South, FY19 Sussex Castle County FINAL BID TAB

Proposals Received 9-Oct-2018 Page 1

Vendor Ranking: Contract was awarded on 11/20/18 to vendor THE GENERAL SHIP REPAIR CORPORATION

ltem No.	Approx Qty	UOM	Description	- 1 -
I	- 1	L.S.	Warranty	\$10,000.00
II	1	L.S.	Transportation	\$37,500.00
A1	1	L.S.	Replace Engine	\$52,150.00
A2	1	L.S.	Replace Belt and Idler Pulleys	\$315.00
A3	1	L.S.	Replace starter and Alternator	\$2,508.00
A4	1	L.S.	Rebuild Transmission Gear Box	\$4,752.00
A5	1	L.S.	Rebuild Hydrostats	\$5,657.00
A6	1	L.S.	Replace Turbo	\$2,185.00
B1	1	L.S.	Replace Battery	\$1,078.00
B2	1	L.S.	Replace Electric Bilge Pump	\$1,772.00
B3	1	L.S.	Replace Multifunction Valves	\$2,107.00
B4	1	L.S.	Replace Shut Off Valves	\$1,322.00
B5	1	L.S.	Rebuild Shut Off Valves	\$440.00
B6	1	L.S.	Drain Fuel Tank for Inspection	\$1,125.00
B7	1	L.S.	Clean Hydraulic Tanks	\$1,588.00
B8	1	L.S.	Coordinate Department Inspection	\$150.00
B9	1	L.S.	Clean Fuel Tank	\$1,125.00
B10	1	L.S.	Replace All Hoses and Sleeves	\$13,145.00
B11	1	L.S.	Repair Manifold Valve	\$2,173.00
B12	1	L.S.	Repair Manifold	\$2,145.00
B13	1	L.S.	Replace Hydraulic Pipe	\$1,967.00
B14	1	L.S.	Install Fill Spout	\$413.00
B15	1	L.S.	Redesign Hydraulic Hose	\$1,429.00
B16	1	L.S.	Replace Fluids	\$5,472.00
B17	450	GAL	Supply Fuel	\$4.00
C1	1	L.S.	Replace All Hoses and Sleeves	\$2,462.00
C2	1	L.S.	Replace Flow Divider	\$1,629.00
C3	1	L.S.	Replace Cylinders	\$5,828.00
C4	1	L.S.	Rebuild Cylinders	\$2,500.00
C5	1	L.S.	Replace Line Bushings	\$2,474.00
C6	1	L.S.	Remanufacture Line Bushings	\$300.00
D1	1	L.S.	Hydraulic Hose Bracket	\$268.00
D2	1	L.S.	Replace All Hoses and Sleeves	\$1,220.00
D3	1	L.S.	Replace Ramp Cylinders	\$3,459.00

Contract No. T201880207.01 FAP No. Various Woodland Ferry Renovations, South, FY19 Sussex Castle County

D4	1	L.S.	Grease Lines and Fittings	\$18,527.00	
D5	1	L.S.	Grease Hinges	\$394.00	
D6	1	L.S.	Replace Rub Plates	\$30,630.00	
E1	1	L.S.	Replace Fairleads	\$8,749.00	
E2	1	L.S.	Replace Hatch Seals	\$2,435.00	
				- 1 -	
E3	1	L.S.	Replace Idler Pulleys	\$3,436.00	
E4	1	L.S.	Grease Idler Pulleys	\$394.00	
E5	1	L.S.	Replace Keel Cooler Anodes	\$516.00	
E6	1	L.S.	Install Anti-Rain Strip	\$2,045.00	
E8	1	L.S.	Install New HVAC System	\$18,193.00	
E9	1	L.S.	Install Metal Day Shapes	\$2,687.00	
E10	1	L.S.	Install Navigation Light System	\$37,337.00	
E11	2300	L.F.	Furnish Cable	\$3.44	
F1	1	L.S.	Dry Docking Plan	\$22,641.00	
F2	5000	S.F.	Light Pressure Wash	\$3.50	
F3	2200	S.F.	High Pressure Wash	\$10.50	
F4	500	S.F.	Rust Removal - Interior	\$13.65	
F5	1100	S.F.	Prime and Paint - Interior	\$5.74	
F6	1070	S.F.	Prime and Paint - Exterior Above Water Line	\$6.33	
F7	2100	S.F.	Prime and Paint - Exterior Below Water Line	\$3.75	
F8	150	S.F.	Prime and Paint - Exterior Thruster Tubes	\$13.13	
F9	120	S.F.	Prime and Paint - Exterior Red Water Line	\$10.80	
F10	280	S.F.	Prime and Paint - Deck Curbing	\$16.07	
F11	1200	S.F.	Prime and Paint - Superstructure and Railings	\$8.26	
F12	1800	S.F.	Prime and Paint - Deck and Ramps	\$18.85	
				\$004 005 00	

	Engineer's Estimate \$2	294,385.00	% Diff
1 - The General Ship Repair Corp., 1449 Key Hwy.,	Baltimore, MD 21230	\$450,348	3.20 52.98%