## Delaware Department of Transportation QUESTIONS AND ANSWERS T201706303.01

Yellow highlighting = previous questions answered in this posting: n/a

## PAVEMENT & REHABILITATION, SUSSEX III, (SR1, DELAWARE SEASHORE) 2017 SUSSEX COUNTY

Thursday, November 09, 2017

<b>Q</b> #	•	Answer	
7	Can a better description for the location of the drainage inlet or outlet pipe be given for the Bedford Avenue pipe flushing/cleanout work?	Not at this time, a field map of the drainage inlets and outlets will be provided at the start of construction.	
	I see no drainage inlet or outlet pipe at Bayberry Lane. Is the outlet pipe or drainage inlet in the swamp area on the south side of Bayberry Lane?	Yes, the pipe is located south of Bayberry Lane in the marsh (bayside). This outfall pipe end will be marked in the field by the start of construction.	
·	Thursday, October 26, 2017		
5	How is the joint sealing per section 401.03-M of the 2016 Standard Specifications paid?	The joint sealing is incidental to the overlay.	
4	Just to clarify, Item 401014 will only be used for tying back pavement on intersecting roads? Can specific locations, limits, and paving depths be provided?	The Type B Bit. Asphalt overlay item no. 401014 is intended to be used to raise a section of the existing pavement grade on the SR 1 mainline. An addendum to replace the "advertised" plan sheets is being issued that will help clarify the intent.	
3	In reference to your answer to question 1 in regards to item 401014 which does not appear in the plans. You refer us to note 11 paragraph A on page 14. This note references entrance and intersection tie-inns. Type B hot mix is not typically used for intersection tie ins. Do we have the correct plans and notes in our bid documents?	This has been corrected in Addendum No. 1.	
	Thursday, October 19, 2017		
	The bid items and quantities in the proposal do not match the items and quantities listed in the plans. Specifically items 401014, 401030, 401036 listed in the proposal are not listed in the plans, and items 401026, 401034 listed in the plan are not listed in the proposal. Please clarify.	This has been corrected in Addendum No. 1.	

<b>Q</b> #	Question	Answer	
Wednesday, October 11, 2017			
	Can the Department provide clarification on how Item 401014, SP TYPE B, PG 64-22, will be utilized on this project? This item isn't mentioned anywhere in the project plans, but is a pay item in the contract.	Please refer to page 14 of 17, note number 11, paragraph A.	