Delaware Department of Transportation

QUESTIONS AND ANSWERS T201780204.01

Stormwater BMP Maintenance NCC, FY 2018 Thursday, April 05, 2018

Q	# Question	Answer	
2	There are a few ponds that have no excavation quantity listed. For instance BMP 137 has no excavation quantity, however it states under note #3 to remove all root zone vegetation to a 2' depth. If this is the case there is over 1,200 cubic yards to be removed. Is this quantity excavation or is this 1,200 yards to be removed under item #201000 - Clearing and Grubbing? If this yardage is to be paid under item #201000 shall we assume that all areas of clearing and grubbing excavation of vegetation to a 2' depth is also to be included and paid under item #201000?	Note #3, which references removal of root zone vegetation to a depth of 2', is to be included and paid for under the lump sum item #201000 for Clearing and Grubbing. There is no separate quantity for excavation of roots or other material in the areas called out for vegetation removal. Line item #201000 for Clearing and Grubbing includes all areas for clearing and grubbing vegetation at all facilities, regardless if there is a line item for excavation at a particular facility.	
	Thursday, March 22, 2018		
1	Is there going to be a line item provided for dewatering of ponds? If not where are we to price the dewatering?	Each pond which requires dewatering has been accounted for under the line item for Riser Dewatering. The contractor should account for the dewatering costs under this item. Additional items related to the dewatering activities, such as dewatering bags and sandbags, have been broken out as separate pay items.	

1 of 1