## Delaware Department of Transportation QUESTIONS AND ANSWERS T201806101.01 Pavement and Rehabilitation, North I, 2018 Eriday, October 26, 2018

Yellow highlighting = previous questions answered in this posting: Q2

Friday, October 26, 2018			
<b>Q</b> #	Question	Answer	
6	801000 maintenance of traffic and 801500 maintenance of traffic, all- inclusive are both listed as pay items. Since signs and drums are also listed as pay items, is the 801500 maintenance of traffic, all-inclusive an error?	associated with location #2. Item 801000 Maintenance of Traffic and	
5	Should there be an item for pinned barrier in concrete for bridge decks?	The guardrail as of right now will not have to be pinned on the bridge decks, if this changes it will have to be addressed after the bid of the contract.	
4	The majority of On/Off Ramps on Location 2 will require closures. Can detour plans be provided?	The topic of ramp closures can be brought up at the preconstruction meeting and if deemed necessary the detour plan process will be discussed at that time.	
3	There is no MOT Guidance for Location 2. The breakout sheet states "to be submitted at Preconstruction Meeting". Does this mean it doesn't get submitted within the typical 7 days of bid?	The contractor's maintenance of traffic plan can be submitted to group 1 construction at the preconstruction meeting or sooner if desired, which at that time it will be reviewed and approved if acceptable.	
	Tuesday, October 02, 2018		
2	Regarding the 14,510' PCC Curb I-IV shown to be placed underneath the new guardrail - this doesn't seem feasible under the current MOT provisions. Without a 24 hr. closure, we would have to remove/replace guardrail same shift, then hand form all of the curb due to limited space to perform the work. This will cause	Addressed in Addendum No. 4.	

<b>Q</b> #	Question	Answer
Wednesday, September 26, 2018		
	Can you please confirm the permanent grass seeding and ECB	The quantity for item 908014 - Permanent Grass Seeding, Dry
1	quantities?	Ground will be corrected to 27,450 SY in forthcoming addendum.
		The quantity for 908020 Erosion Control Blanket Mulch is correct.