

Delaware Department of Transportation

**QUESTIONS AND ANSWERS**

**T201906107.01**

**PAVEMENT & REHABILITATION, NORTH VII, 2019, NEW CASTLE COUNTY**

**Friday, November 15, 2019**

Q #	Question	Answer
1	What is the depth of patching (item 401031) – no detail provided in plans? Will it be based on matching existing pavement thickness? Is this information available?	Patching is presumed to be 6” in depth unless field conditions warrant adjustment to depth.