

Delaware Department of Transportation

**QUESTIONS AND ANSWERS**

**T201900702.01**

**SR 7 MEDIAN BARRIER REPLACEMENT, NEW CASTLE COUNTY**

**Friday, April 12, 2019**

Q #	Question	Answer
2	Contract calls for 24 each of Item #809007 Sand Crash Cushion Array. The placement of the Sand Crash Cushion Array is shown on Plan Drawings Sheet #18 & Sheet #21, however the notes on the Plans Sheets call for a "non-gating redirective attenuator." According to the manufacturer's description, Sand Crash Cushions are not non-gating and not redirective.	Item #809007 Sand Crash Cushion Array is not intended to be an attenuator. Item #809007 Sand Crash Cushion Array is used to protect the work zone. The temporary impact attenuator, as called for in the plans, will be needed to protect the blunt end of the temporary PCC safety barrier.

**Tuesday, April 09, 2019**

1	We are questioning the quantity on Item 846001 – Furnish & Install Loop Wire. Quantity on the bid sheet is 10 ft. Should this possibly be 100 ft.? 10 ft. is not enough for a single 6 x 6 loop.	We are assuming no impacts to the existing signal conduit. This quantity was used to account for a possible splice in the loop in the event one of the proposed drainage inlets impacts this system.
---	--	--