

Delaware Department of Transportation
QUESTIONS AND ANSWERS
T201407403.01

Yellow highlighting = previous questions answered in this posting: Q4

BR 1-577 on N050 Northeast Boulevard over Brandywine River
Tuesday, October 09, 2018

Q #	Question	Answer
Friday, October 05, 2018		
4	Regarding Item 201500, CLEANING OF PATHOGENICALLY CONTAMINATED STRUCTURE, there are no details within the plans that would help determine the extent of the pathogenical contamination at the structure. A site visit only provides partial access to the structure. Do you have an inspection report that would detail how extensive the contamination is ? Would you consider changing this item to a fixed price due to the unknown nature of the required work?	The contract item 201500, CLEANING OF PATHOGENICALLY CONTAMINATED STRUCTURE is intended for cleaning the interior surfaces of the Operator's House to facilitate performance of contract work. Please refer to the photos posted to the website for a partial view of the interior conditions as well as the original contract drawings for details and dimensions.
3	Note 13 on plan sheet 10 refers to "original design drawings". Can those drawings be provided to the bidders?	The original drawings have been posted to the website.
Monday, October 01, 2018		
2	# 850531 Luminaire arms special provision: arms are to match material of signal pole. Please provide material of signal pole (steel or aluminum).	The signal pole material is steel.
Tuesday, September 25, 2018		
1	In accordance with the supplemental update to the 2016 Standard Specifications should there be an item for curb ramps?	For this project curb ramps will be paid under P.C.C. sidewalk.